




















K30  24	T1  20	M1  20	SM  4	STB  10	X  20	KM  1	W3,5x16  2
KF  4	W4x16  21	UM  2	W3x13  4	E5x13  16	PS  16	ODB  1	
Q  1	X1  4	MF  10	TJ  10	PZ  2	ZP  2	M4x9  10	 1





M1	K30	T1
		
4	4	8






W3,5x16	ODB	M1	K30	T1	E5x13	PS
						
2	1	4	4	2	4	8









PZ	M1	K30	T1	E5x13	PS
					
2	4	4	2	4	8













M4x9	MF	TJ
		
10	10	10



ZP	W4x16
	
2	4







4	10	16

