
















K30  16	T1  16	M1  16	Z15  4	PZ  4	X  16	RN  2	STB  10
W3x16  8	W4x16  33	UM  2	W3x13  4	PP  4	NR  2	SM  4	MS  1


PZ	T1
	
4	16








M1	K30
	
8	8







 SM 4	 NR 2	 W4x16 24
 STB 10		



W4x16










SM

W4x16

SR

A=B

STB



1

2

3

4

X
16

W3x13
4

W3x16
8

RN
2

UM
2

