












80 D 2F ZB



	B		E1		A		O		S23		U		P7		J		L1		G		H		P5		F2
8		8		8		1		2		4		10-15		4		1		4		4		8		4	
Ø4,0x35mm		Ø4,0x45mm								M4,0x22mm		Ø3,0x20mm										Ø3,5x13mm			
R3		P4		E9																					
4		2		2																					



The diagram illustrates the final assembly step. A screwdriver is shown driving a screw (P5) into a bracket (G). A circular inset provides a magnified view of the screw head (P5) seated within the bracket's hole (G).



ISM-KUH-00120