








100



 A 8	 B 12	 C 1	 D 30-40	 E 4	 F 4	 H 44	 O 4
 S 2	 T 6	 U 4					



zmiar przekatną



100

