


ASSEMBLY INSTRUCTIONS

MATERIALS CAREFULLY.FOR SMALL PARTS.WHICH MAY HAVE COME LOOSE INSIDE THE CARTON.
DURING SHIPMENT.IDENTIFY AND COUNT ALL PARTSAND COMPARE WITH THE HARDWARE
LIST AND PARTSLIST.



A		M8*65MM	6
B		M8*50MM	8
C		M6*55MM	3
D		M8	8
E		M8	14
F		5#	1
G		5#	1
H			24
I			24
J			12
K			3
L			4

