








CHECK TYP 10


























10




NO	Dim.		Col.-No	Qty
1	280	306	1	4
2	970	284	1	4
4	244	246	1	4
5	982	258	1	2
6	884	274	1	2
7	246	60	1	4


CHECK TYP 10

A1 x32  Ø8x36	B4 x16 	B5 x16  Ø15x12	G5 x16 	S1 x12 	G7 x16 
E21 x4 Ø35 H=0 	E2 x4 H=0 	D10 x8 USØ3,5x13 	ZR1 x4 	D6 x8 USØ3,5x30 	





A1		B5		G7	
x16	ø8x36	x16	Ø15x12	x16	

1









2


A1		B4	
x16	ø8x36	x16	



3



4




G5

x8




5



6

G5

x8




CHECK TYP 10

7



$X=Y$ $\uparrow 90^\circ$


S1	
x12	









8

ZR1	
x4	



D6	
x8	USØ3,5x30




9




x2






10 - 11



12 - 13




10







E2

x2







H=0

11



12



13

