







2

Diagram 2 shows the assembly of the top panel. A circular inset shows a 'ZA' (Zinc Anode) sacrificial anode. The main diagram shows a screwdriver being used to secure the top panel (2) onto the vertical frame (1). Arrows indicate the direction of assembly.

3

Diagram 3 shows the assembly of the side panel. A hammer is used to secure the side panel (4) onto the vertical frame (1). A 90° angle is indicated for the side panel's orientation.

Diagram 3 shows a hammer being used to drive the bottom rail (1) into the side rail (4). A 90-degree angle is indicated between the two rails.