











|                     |              |              |                      |               |                        |                 |             |
|---------------------|--------------|--------------|----------------------|---------------|------------------------|-----------------|-------------|
| K30<br><br>26       | T1<br><br>20 | M1<br><br>20 | X<br><br>20          | STB<br><br>10 | SM<br><br>4            | J<br><br>3      | GW<br><br>6 |
| 5x9<br><br>F1<br>12 | KF<br><br>12 | Q<br><br>1   | 4.0x30<br><br>H<br>8 | PP<br><br>8   | 3,5x16<br><br>F3<br>12 | L<br><br>R<br>3 |             |





4/5

