












H200






K30  20	T1  20	M1  20	ZP  2	PZ  2	UM  2	PZR  2
STB  12	M25  2	W4x16  10	Z1  20	KS  6	PS  5	ZRA  2

PS 	T1 	KS 
1	8	6



PZ 	K30 	M1 
2	8	8

PS 
8





ZP

W4x16

8

7

ZRA



3

6

6

4

H

