







FERIDO

Szafka nocna





No	T(mm)	L(mm)	W(mm)	pcs.
1	16	400	400	1
2	16	400	400	1
3	16	368	400	1
4	16	368	400	1
5	16	366	328	1
6	16	362	225	1
7	16	300	110	1
8	16	300	110	1
9	16	308	110	1
10	3	321	297	1
11	3	375	377	1



















Diagram illustrating the assembly of the base plate (1) using screws (M1) and a support structure.



A schematic diagram of a mechanical assembly. A motor, labeled 'M', is shown at the top, connected to a horizontal shaft. This shaft passes through a rectangular block and is connected to a vertical shaft. The vertical shaft is connected to a cylinder, labeled 'K', which is positioned below the block. The entire assembly is enclosed in a rounded rectangular frame.

3




4









7



8



9



10

