







†8x30mm  A 28	†6x42mm  B2 6	†15/12mm  C 16	†12/10mm  C5 6	L=20mm  D2 22	 E 4	L=180mm  F32 4	†35/16mm  HG2 2	27/310mm  I4 3	†5/16mm  J3 4	
 J12 1	 L 16	 L9 1	†6,3x13mm  M2 12	†10x50mm  O7 1	†4.0x16mm  P1 16	†3.5x13mm  P5 5	†3.0x20mm  P7 4	†4.0x30mm  R2 8	L=96mm  S 4	M4x9mm  U1 6


ISM-VIS-004



	Ersatzteil Nummer	Dimension
	VIS.106	560x399x16
	VIS.107	560x399x16
	VIS.504	560x377x16
	VIS.207 x2	1000x400x16
	VIS.902 x2	475x100x16
	VIS.301	474x340x16
	VIS.606	975x569x2,5
	VIS.607 x3	452x327x2,5
	WST.0183 x3	330x100x12
	WST.0184 x3	330x100x12
	WST.0275 x3	441x100x12
	VIS.705 x3	168x471x16
	VIS.706	552x471x16




VIS.207-G



VIS.207-D






VIS.301




VIS.607

1


$\pm 12/10\text{mm}$  C5 6	$\pm 8 \times 30\text{mm}$  A 12
--	--



x3





2



x3



$\pm 6 \times 42\text{mm}$  B2 6




3

$L=20\text{mm}$  D2 6
--








x3




4






x3















5



x3






$\pm 8 \times 30 \text{ mm}$  A	$\pm 15/12 \text{ mm}$  C	$L=20 \text{ mm}$  D2	$27/310 \text{ mm}$  I4	$\pm 6,3 \times 13 \text{ mm}$  M2
16	16	4	3	12





7

L=20mm  D2 6	L=180mm  F32 4	4.0x16mm  P1 16
---	---	--





8



L=20mm  D2 6
--













9












10



$\varnothing 3.0 \times 20 \text{ mm}$  P7 4	 L 10
---	---






$\varnothing 10 \times 50 \text{ mm}$  O7 1	 L9 1	$\varnothing 3.5 \times 13 \text{ mm}$  P5 1
---	--	--









13

	$\pm 5/16\text{mm}$ 	
J12	J3	E
1	4	4





14

L=96mm 	$\pm 4.0 \times 30\text{mm}$ 	M4x9mm 
S	R2	U1
3	6	6



15

$\varnothing 35/16\text{mm}$	$\varnothing 3.5 \times 13\text{mm}$
	
HG2	P5
2	4



16

L=96mm	$\varnothing 4.0 \times 30\text{mm}$
	
S	R2
1	2

