





VEGAS 2




Narzędzia potrzebne do montażu




UWAGA !!!

MONTOWANIE USZKODZONYCH
ELEMENTÓW POWODUJE UTRATĘ
GWARANCJI




Nr	D[mm]	S[mm]	G[mm]	Ilość
1	1082	407	48	1
2	1082	407	48	1
3	783	405	48	1
4	780	388	16	1
5	783	405	48	1
6	394	320	16	1
7	773	368	16	1
8	1070	834	2,5	1
9	603	190	16	4
10	546	165	16	4
11	350	165	16	4
12	350	165	16	4
13	575	355	2,5	4

W przypadku reklamacji proszę podać numer pakowacza znajdujący się na kartonie.




Y - 2 St.




Q - 4 St.
3,5x16 mm



M - 65 St.
3x30 mm



F - 16 St.




P - 4 St.



N - 10 St.
4x30 mm




U - 5 St.




G - 4 St.
3,5x16 mm




L - 12 St.



T - 4 Kpl.



C - 2 St.



D - 2 St.




S - 1 St.




E - 55 St.



B - 28 St.



K - 12 St.





Z - 1 St.



J - 32 St.
5x13 mm















This exploded view diagram illustrates the assembly of a cabinet. The components are labeled as follows:

- 1**: Top panel, shown with six screws (**K**) for attachment.
- 2**: Bottom panel, shown with six screws (**K**) for attachment.
- 3**: Left side panel, featuring four cam bolts (**L**) and four cam locks (**P**).
- 4**: Middle divider panel, featuring four cam bolts (**L**) and four cam locks (**P**).
- 5**: Right side panel, featuring four cam bolts (**L**) and four cam locks (**P**).
- 6**: Back panel, shown as a separate piece.
- T**: Top hinge, shown attaching to the top panel and side panels.
- J**: Joint or hinge, shown attaching to the middle divider panel and side panels.
- B**: Bolt or screw, shown attaching to the right side panel.
- C**: Corner bracket or hinge, shown attaching to the right side panel.





III

55X 



IV



MONTAŻ/DEMONTAŻ PROWADNIC

