










ASSEMBLY INSTRUCTIONS

MATERIALS CAREFULLY.FOR SMALL PARTS.WHICH MAY HAVE COME LOOSE INSIDE THE CARTON.
DURING SHIPMENT.IDENTIFY AND COUNT ALL PARTSAND COMPARE WITH THE HARDWARE
LIST AND PARTSLIST.



A		M8*50MM	8
B		M8	8
C		M8	8
D		5#	1
E		5#	1
F			24
G			12
H			4

