

ASSEMBLY INSTRUCTIONS

MATERIALS CAREFULLY. FOR SMALL PARTS WHICH MAY HAVE COME LOOSE INSIDE THE CARTON DURING SHIPMENT IDENTIFY AND COUNT ALL PARTS AND COMPARE WITH THE HARDWARE LIST AND PARTS LIST.



A		M8*65MM	6
B		M8*50MM	8
C		M6*55MM	3
D		M8	8
E		M8	14
F		5#	1
G		5#	1
H			24
I			24
J			12
K			3
L			4

