









TREND II.T.WIT-50



G4



4x16

x12

F2



x12

K1



ø15x12

x12

W4



1,6x20

x50


B1



ø8x35

x18

P45



120mm

x4


G34



3,5x16


x8

K5



x12


D4



PZ350D

x4


C4



Z350D

x4


G3




4x30

x4

①



②



③

