






CHECK TYP 30











30

















120 min

NO	Dim.		Col.-No	Qty
1	1752	370	1	1
2	1752	370	1	1
3	226	348	1	1
4	226	348	1	1
5	226	328	1	1
6	226	328	1	1
7	582	180	1	2
8	578	318	1	1
9	568	238	1	2
10	592	238	1	1
11	554	60	1	2


CHECK TYP 30

A1 x24  Ø8x36	B4 x8 	B5 x8  Ø15x12	G5 x8 	B11 x8  Ø7x50	L1 x2 
E25 x4  Ø35 H=16	E4 x4  H=2	D10 x18  USØ3,5x13	G21 x2 	D7 x6  USØ3x16	G7 x4 
I11 x6  Ø50, h=25	UP15 x6  UPØ4x25	S1 x14 	G16 x2 	UP13 x2  UPØ3x16	






1

A1	 ø8x36	B5	 Ø15x12
x8		x4	




2

A1		B5		G7	
x8	ø8x36	x4	Ø15x12	x4	





A1

x8



3



4

I11

x6






UP15

x6





E4

x4








5

B4	
x8	




6


E25		D10	
x4	Ø35 H=16	x8	USØ3,5x13



7






8





9




10

$X=Y$ 90°




S1

x14




G16

x2






UP13






x2






UPØ3x16






11



12





13

