










3

Diagram 3 illustrates the third step of the assembly process. It shows the side panels (1) and the front panel (2) already in place. The top panel (5) and bottom panel (4) are being attached to the side panels. The diagram includes callouts for the top panel (5) and bottom panel (4), and the side panels (1) and front panel (2). Arrows indicate the direction of assembly. A callout shows a ZA logo and a screwdriver icon, indicating the use of a screwdriver to secure the panels. A callout shows a ZA logo and a screwdriver icon, indicating the use of a screwdriver to secure the panels.

4

Diagram 4 illustrates the process of attaching the bottom panel (1) to the side panel (7). A hammer is used to drive screws (F) into the bottom panel. A screwdriver (S3) is used to tighten the screws. A 90-degree angle is indicated for the screws. The side panel (7) is shown with a 90-degree angle indicated by a curved arrow.

5

6

This diagram illustrates the sixth step of the assembly process. It shows a partially assembled cabinet with the top panel (14) being attached to the main body. The side panel (3) is also shown being attached to the side of the cabinet. The diagram includes callouts for screws (U, T, BL) and a screwdriver icon, indicating the tools and components needed for this step.