












"80" / "90"



 4.0x13mm C	 4.0x37mm D	 F	 G	 H
12	4	1	2	2
 I	 J	 K	1.	
3	4	3		
 L	 M	 N		
1	2	2		




2.




Górna część
drzwi - brak
okleiny ABS

The upper
part of the
door - lack
veneer ABS



Oberer Teil
der Tür - kein
ABS-Furnier





3.





4.





5.




**OPCJA DODATKOWA
ADDITIONAL OPTION
ZUSÄTZLICHE OPTION**






6.




7.




8.







10.



9.



1



N
N

